



Handling HMI 12/18/24KW HMI Globes



GLOBE MOUNTING PROCEDURE



A. TO OPEN SOCKET, PULL DOWN ON LATCH BEFORE REMOVING OLD GLOBE

B. NOTE POSITION OF RIBBON

C. AND DIMPLE, FACING FORWARD

D. INSTALL NEW GLOBE IN SAME POSITION MAKING SURE GLOBE IS CENTERED IN BETWEEN SOCKETS
CLOSE LATCHES

E. ATTACH GLOBE LEADS TO H.V. TERMINAL BLOCKS

WARNING!

IMPORTANT! AVOID BLOWOUTS!

DO NOT ALLOW LEADS TO CONTACT SIDE OF LAMP HEAD!

